


Analysis of deformation of breakwater during earthquakes

(Damage to a breakwater at Kobe port during 1995 Hyogoken-Nambu earthquake)



The analysis results in settlement of breakwater, associated with lateral spreading of rubble mound.

