



Analysis of deformation of deep foundation (pneumatic caisson foundation) during earthquakes

Damage to Kobe Ohashi Bridge during 1995 Hyogoken-Nambu earthquake is analyzed.



Yellow marker indicates large pneumatic caisson foundation (33m from top to bottom).



Damage to Kobe Ohashi Bridge during 1995 Hyogoken-Nambu earthquake